





# 形鋼のゲージ

## 形鋼のゲージ



| <i>A</i> または <i>B</i> | $g_1$ | $g_2$ | 最大軸径 | <i>B</i> | $g_1$ | $g_2$ | 最大軸径 | <i>B</i> | $g_3$ | 最大軸径 |
|-----------------------|-------|-------|------|----------|-------|-------|------|----------|-------|------|
| 45                    | 25    |       | 12   | 100      | 56    |       | 16   | 50       | 30    | 12   |
| 50                    | 28    |       | 16   | 125      | 75    |       | 16   | 65       | 35    | 20   |
| 60                    | 35    |       | 16   | 150      | 90    |       | 22   | 70       | 40    | 20   |
| 65                    | 35    |       | 20   | 175      | 105   |       | 22   | 75       | 40    | 22   |
| 70                    | 40    |       | 20   | 200      | 120   |       | 24   | 80       | 45    | 22   |
| 75                    | 40    |       | 22   | 250      | 150   |       | 24   | 90       | 50    | 24   |
| 80                    | 45    |       | 22   | 300      | 150   | 40    | 24   | 100      | 55    | 24   |
| 90                    | 50    |       | 24   | 350      | 140   | 70    | 24   |          |       |      |
| 100                   | 55    |       | 24   | 400      | 140   | 90    | 24   |          |       |      |
| 125                   | 50    | 35    | 24   |          |       |       |      |          |       |      |
| 130                   | 50    | 40    | 24   |          |       |       |      |          |       |      |
| 150                   | 55    | 55    | 24   |          |       |       |      |          |       |      |
| 175                   | 60    | 70    | 24   |          |       |       |      |          |       |      |
| 200                   | 60    | 90    | 24   |          |       |       |      |          |       |      |

# 形鋼のゲージ



## 形鋼のゲージ具体例 M16

